

**BUTLER COUNTY BRIDGE MANAGEMENT SYSTEM
BRIDGE INSPECTION RECORD**

County Bridge Name:
BAUER ROAD - 0.807

Photo 1



ELEVATION

Photo 2



ENDVIEW

Structure File Number:	0931160	Inspected By:	ROGER E. THOMPSON
General Appraisal Operating Status:	4 A	Inspection Date:	0 6 / 2 6 / 0 5
Sufficiency Rating:	44.8	Township:	MILFORD
Inspection No:	2005		

STRUCTURE INFO

NO. OF SPANS:	1	O.A. LENGTH:	36 FT.	DECK WIDTH:	20 FT.
YEAR BUILT / REHAB:	1969				
STRUCTURE TYPE:	STEEL BEAM ON WALL TYPE AND STONE ABUTMENTS				

INSPECTION FINDINGS

DECK COMMENT:	MAJOR SPALLING AND EXPOSED REBAR ON UNDERSIDE OF DECK.
SUPERSTRUCTURE COMMENT:	MAJOR DETERIORATION.
SUBSTRUCTURE COMMENT:	MINOR FLAWS IN CONCRETE AND STONES OF ABUTMENTS
CULVERT COMMENT:	
SCOUR COMMENT:	
CHANNEL COMMENT:	
APPROACH COMMENT:	

RECOMMENDED MAINTENANCE

COMPONENT	PRIORITY	DESCRIPTION
CONCRETE		
STEEL	L	REPLACE STRUCTURE. LOAD RATE STRUCTURE & PLACE POSTING IN MEANTIME.
GUARDRAIL		
PAVEMENT		
EMBANKMENT		
CHANNEL	L	DIVERT CHANNEL FROM FORWARD ABUTMENT.
EROSION		

0931160

SRUCTURE FILE NUMBER

BRIDGE NUMBER BUT T0066 0081 MILFORD YEAR BUILT 1969
CO ROUTE UNIT VILLAGE/TOWN

DIST. 8 BRIDGE TYPE Steel Beam Simple Span TYPE SERVICE 115 BUTLER

Table with columns for item number, description, and rating. Includes sections for DECK, SUPERSTRUCTURE, SUBSTRUCTURE, CULVERT, CHANNEL, APPROACHES, and GENERAL.

67. INSPECTED BY

ROGER E. THOMPSON
PE# 41434
ME COMPANIES

PE INITIALS

68. REVIEWED BY

PE#

PE INITIALS

DATE 0 6 2 6 0 5

0 0 0 0 N N N 1

69 SURVEY

DATE

